

# PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

(to be filled by the head of school/institute)

1. Name of the school THE SHRIRAM UNIVERSAL SCHOOL, BLOCK-D
2. Location BEHIND MAIN MARKET, SARABHA NAGAR, LUDHIANA
3. Plot Area 2 ACRES
4. Plinth Area GROUND FLOOR, 22344. FIRST FLOOR- 22344
5. Number of Storey GROUND + FIRST FLOOR
6. Year of Construction of building 2018
7. Supervision of the qualified engineer  
the following details may be given
  - a) Name of the engineer JAITLEY ASSOCIATES CONSULTING ENGINEER
  - b) Address E-60, 2ND FLOOR, MASJID MOH. GREATER
  - c) Set of structure drawing used KAILASH - III - NEW DELHI  
in the construction if available
  - d) Name of the Architect DEBASHISH LINE AND FORM ARTITECTS
8. Whether the building has been constructed for the purpose of : SERVICES (P) LTD.
  - a) school YES
  - b) residential purpose and converted  
for use as a school NO
9. Materials used for Roof :
  - a) RCC slabs YES
  - b) PS joints and battens NO
  - c) Wooden joints and battens NO
10. Materials used for Walls :
  - a) Mud Mortar NO
  - b) Cement Mortar YES
  - c) Plaster (i) Lime Mortar NO  
(ii) Cement Mortar YES
11. Flooring :
  - a) Conglomerate YES
  - b) Terrazo NO
  - c) Brick Paving NO
12. Details Drawing Indicating dimensions  
of the rooms along with size and location  
of doors and windows

Signature with Stamp of  
The Head of the School/Institute

Principal  
The Shriram Universal School,  
Block-D, Sarabha Nagar,  
Behind main Market, Ludhiana

PART - II

(TO BE FILLED BY THE SDO OF PWD B&R DEPTT.)


- a) I have visited the above mentioned school on 10/04/24 and have visited by inspected it from all angle of safety and I find it fit for normal use a school building.
- b) In case any addition / alteration or expansion and modification to this building is to be carried out, the same be carried out under the supervision of a technically qualified engineer and this certificate may again be after the completion from the under signed.
- c) In case the building is affected by flood it there is settlement of wells / foundations or safing of roofs etc. Immediately inspection of the undersigned be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (Indicate year upto which it can be used) 31/03/2025 / March 2025

Receipt No - 11057808

Date - 09/04/24

Enset No 24

Date 12/04/24

  
Division Engineer  
Provincial Sub. Div. No.2,  
PWD B & R, Ludhiana